
HECHNICAL BULLETINGONTAINED

TB-076 • July 2022

What to do if your fifth wheel pull handle is bent?

The Fontaine Fifth Wheel pull handle is crucial to the proper operation of the locking mechanism and if found to be damaged should be replaced. Any attempt to straighten the pull handle could cause a malfunction such as excessive slack, hard to open, and/or partial close of the locking mechanism.





Never try to straighten a bent or broken pull handle. Replace with kits shown below.



The above bent handle is no longer usable and must be replaced.

Pull handle replacement kits

